



Lufttüchtigkeitsanweisung (LTA) Consigne de Navigabilité (CN) Direttive sulla Navigabilità (DN) Airworthiness Directive (AD)		FOCA AD <b>HB-2016-001</b>
Inkraftsetzung Mise en vigueur Entrata in vigore Effective Date	<b>17 May 2016</b>	<b>Pilatus – PC-7</b> FOCA TC/TCDS No: F 56-20

**Issue Date:** 03 May 2016

**ATA Chapter:** ATA 53 – Fuselage

**Subject:** **Fuselage – Main Frames – Frame 11 Fittings – Inspection**

**Supersedure / Revised AD(s):** Not applicable

**Type Certificate Holder's Name:** Pilatus Aircraft Ltd.

**Manufacturer(s):** Pilatus Aircraft Ltd.

**Applicability:** Model PC-7 aircraft, Manufacturers Serial Numbers (MSN) 101 through MSN 618.

**Reason:** This Airworthiness Directive (AD) is prompted due to a report of Stress Corrosion Cracking (SCC) on the Main Frame on Frame (FR) 11 left fitting Part Number (P/N) 112.35.07.489 and right fitting P/N 112.35.07.490.

Such a condition, if left uncorrected, could lead to potential loss of the horizontal stabilizer.

In order to correct and control the situation, this AD requires a one-time check to identify the material specification and inspect the affected areas of the airframe that are made of aluminium alloy AA2024-T351. Any structural parts of the aircraft structure found to be cracked must be reported to Pilatus prior to further flight.

**Required Action(s) and Compliance Time(s):** Required as indicated below, unless already accomplished:

- (1) Within the next 120 days after the effective date of this AD, perform a test to identify the material specification of the left and right fittings P/N 112.35.07.489 and P/N 112.35.07.490 as required by paragraph (§) 3.B. of PILATUS PC-7 Service Bulletin No. 53-013.
- (2) If during the inspection required by § (1) of this AD, fittings made of aluminium alloy AA2124-T851 are found, report the inspection results as required by § 3.D. of PILATUS PC-7 Service Bulletin No. 53-013.
- (3) If during the inspection required by § (1) of this AD, fittings made of aluminium alloy AA2024-T351 are found, before next flight after the effective date of this AD, perform an inspection for cracks as required by § 3.C. of PILATUS PC-7 Service Bulletin No. 53-013 for cracks. No cracks are allowed.

Lufttüchtigkeitsanweisung (LTA)  
Consigne de Navigabilité (CN)  
Direttive sulla Navigabilità (DN)  
Airworthiness Directive (AD)

FOCA AD  
**HB-2016-001**

**Note 1:** The Aircraft Maintenance Manual (AMM) Temporary Revision (TR) No. 05-34 introduces a scheduled maintenance interval of 12 months to check for cracks at the FR 11 fittings made of aluminum alloy AA2024-T351.

- (4) If during the inspection required by § (3) of this AD, cracks are found, prior further flight, replace the fittings in accordance with the instructions given in PILATUS PC-7 Service Bulletin No. 53-014.

**Ref. Publication(s):** PILATUS PC-7 Service Bulletin No. 53-013, initial issue.  
PILATUS PC-7 Service Bulletin No. 53-014, initial issue.

The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.

**For further information contact:** The applicable manufacturer's documentation may be obtained directly from:

PILATUS AIRCRAFT LTD.  
Customer Technical Support (MCC)  
P.O. Box 992  
CH-6371 Stans, Switzerland

Tel.: +41 (0)41 619 67 74 Fax: +41 (0)41 619 67 73  
E-mail: [Techsupport@pilatus-aircraft.com](mailto:Techsupport@pilatus-aircraft.com)

For further information contact:

FEDERAL OFFICE OF CIVIL AVIATION (FOCA)  
Design and Production (STEH)  
CH-3003 Bern, Switzerland

E-mail: [airdir@bazl.admin.ch](mailto:airdir@bazl.admin.ch)