

Service Bulletin No: 32-031

Ref No: 492

Modification No: EC-26-0119

ATA Chapter: 32

**LANDING GEAR - WHEELS AND BRAKES  
MODIFICATION TO REPLACE THE LH AND RH BRAKE PIPES****1. Planning Information****A. Effectivity**

PC-12/47G series aircraft MSN 3001 thru MSN 3058, MSN 3060 and MSN 3062.

**B. Concurrent requirements**

None.

**C. Reason****(1) Problem**

Due to an issue seen during production, the provisions for the Emergency Autoland (EAL) braking system (brake pipe going to the EAL Brake Shuttle Valve (BSV) and the brake pipe going from the BSV to the landing gear) need to be replaced with previously certified brake pipes.

**(2) Solution**

On both LH and RH side the brake pipes, provisioned for EAL, are modified as follows:

- The pipe going into the EAL BSV, and the pipe going from the BSV to the landing gear are to be removed and replaced by the previously certified pipes
- The shuttle valves (LH and RH) remain installed and the ports are to be capped
- Provision fittings for EAL remain installed on the shuttle valves.

**D. Description**

This Service Bulletin gives the data and instructions necessary to do the modification to replace the brake pipes.

**E. Reason for revision**

Not applicable.

**F. Compliance**

Mandatory.

To be embodied no later than 28 days from the Issue date of this Service Bulletin.

**G. Approval**

The technical content of this document is approved under the authority of the DOA ref. EASA.21J.357.

Pilatus advises Operators/Owners to check with their designated Airworthiness Authority for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

**H. Copyright and legal statement**

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

In connection with the use of this document, Pilatus does not provide any express or implied warranties and expressly disclaims any warranty of merchantability or fitness for a particular purpose. This document contains trade secrets, confidential and/or proprietary information of Pilatus and technical data subject to export control laws and regulations, including the U.S. Export Administration Regulations (EAR). Disclosure or distribution of this document contrary to the EAR, and other laws and regulations, is strictly forbidden. The above restrictions may apply to data on all pages of this document.

**I. Manpower**

<b>Description</b>	<b>Man-Hours</b>
Preparation	0.25
Modification	2.00
Close up	0.75
<b>TOTAL MAN-HOURS</b>	<b>3.00</b>

**NOTE:** The man-hours do not include the time necessary to cure sealants, paints and adhesives.

**J. Weight and balance**

Negligible.

**K. Electrical load change data**

Not changed.

**L. Software**

Not changed.

**M. References**

Aircraft Maintenance Manual (AMM)

12-B-20-20-01-00A-040A-A

12-B-20-31-00-00A-070A-A

12-B-32-40-00-00A-902A-A

Tool and Equipment Manual (TEM)

12-B-00-00-00-00A-060A-A

**N. Publications affected**

Illustrated Parts Data (IPD).

**O. Interchangeability of parts**

Not Interchangeable.

**2. Material Information**
**A. Material - Price and availability**

Operators that require additional information and/or Service Bulletin material can contact their authorized Pilatus Service Center, or Pilatus Customer Support on: <https://www.pilatus-aircraft.com> → contact us.

**NOTE:** Part numbers given in this Service Bulletin are correct at the time of approval. Pilatus Aircraft Ltd reserves the right to change the part numbers as necessary. Part numbers of items delivered are correct when dispatched. This could lead to differences between those part numbers quoted in this Service Bulletin and the delivered parts, if parts are superseded. Operators are requested to check the Illustrated Parts Data (IPD) for delivered parts that differ from those listed in the Service Bulletin Materials List.

Operators are requested to advise Pilatus Aircraft Ltd of the Manufacturer's Serial Number (MSN), the flying hours and landings of aircraft that are allocated for this Service Bulletin.

**B. Warranty**

Credit will be issued for parts and labour for all affected aircraft on approval of a warranty claim, provided the work is accomplished by an authorized Service Center no later than 2 months from the issue date of this Service Bulletin.

**C. Material necessary for each aircraft**

**NOTE:** Referenced AMM procedures may contain additional materials to be procured.

**(1) Material to order from Pilatus**

Modification kit number	Price	Availability
500.51.12.091	Contact as above	Approximately 2 weeks

**Modification kit P/N 500.51.12.091**

New part No.	Description	Old part No.	Qty	Disp. code	Fig	Item
532.42.12.137	PIPE ASSY, HYDRAULIC, LH	-	1	N	1	10
		532.42.12.174	1	D	1	2
		532.42.12.173	1	D	1	3
532.42.12.139	PIPE ASSY, HYDRAULIC, RH	-	1	N	1	11
		532.42.12.176	1	D	1	8
		532.42.12.175	1	D	1	6
946.29.15.835	FITT, CAP, ASSY	-	4	N	-	-

Disposition Codes: D - Discard / N - New / R - Return to Pilatus / E - Exchange Part

**(2) Additional material to procure**

None.

**(3) Locally supplied materials**

**NOTE:** Referenced AMM procedures may contain additional consumables to be used.

To identify the materials used in this procedure, look in the Consumable materials list. Refer to AMM 12-B-20-31-00-00A-070A-A.

Material No.	Description	Qty	Remarks
P02-031	Absorbent paper	AR	Or equivalent
P10-006	Hydraulic fluid AeroShell Fluid 31	AR	-

**D. Material necessary for each spare**

Not applicable.

**E. Re-identified parts**

Not applicable.

**F. Tools and equipment**

**NOTE:** Referenced AMM procedures may contain additional tools to be used.

To identify the AGE and tools used in this procedure, look in the list of AGE and tools. Refer to TEM 12-B-00-00-00-00A-060A-A.

Tools and equipment	Recommended Pilatus part
Tool kit, mechanic	Local supply
Brake bleeding rig (TEM Tool No. T32-070 or T32-140)	-
Brake bleeding adapter kit (TEM Tool No. T32-075)	-
Safety clip (TEM Tool No. T12-030)	-

**3. Accomplishment Instructions**

**WARNING:** BE CAREFUL WHEN YOU DO WORK ON THE ELECTRICAL SYSTEM OR A SYSTEM THAT USES ELECTRICAL POWER. MAKE SURE THAT IT IS SAFE BEFORE YOU APPLY ELECTRICAL POWER TO THE AIRCRAFT OR ENERGIZE THE AIRCRAFT ELECTRICAL SYSTEMS. ELECTRICAL POWER CAN CAUSE DEATH OR INJURY TO PERSONNEL AND / OR DAMAGE TO EQUIPMENT.

**WARNING:** BE CAREFUL WHEN YOU USE THE CONSUMABLE MATERIALS. OBEY THE MANUFACTURER'S HEALTH AND SAFETY INSTRUCTIONS AND ALL THE APPLICABLE LOCAL INSTRUCTIONS. CONSUMABLE MATERIALS CAN BE DANGEROUS AND CAN CAUSE DEATH OR INJURY TO PERSONNEL AND / OR DAMAGE TO EQUIPMENT.

**NOTE:** All torque related information necessary for this procedure is given in the standard practices. Refer to AMM 12-B-20-20-01-00A-040A-A.

**A. Preparation**

- (1) Put chocks in front of and behind the LH and RH main wheel.
- (2) Set the parking brake handle to ON but do not apply brake pressure with the brake pedals.
- (3) Open access panels 21PZ, 12EL and 12ER.

**B. Modification****Refer to Figure 1**

- (1) Left EAL BSV modification:
  - (a) Put absorbent paper (Material No. P02-031) below the brake shuttle valve (5) at wing rib 1.
  - (b) Disconnect and remove the hydraulic pipe assembly (2) (P/N 532.42.12.174) from between the fitting on wing rib 1 (1) and the brake shuttle valve (5).
  - (c) Disconnect and remove the hydraulic pipe assembly (3) (P/N 532.42.12.173) from between the brake shuttle valve (5) and the fitting on the fuselage (4).
  - (d) Install a new cap assembly (P/N 946.29.15.835) on the two empty brake shuttle valve (5) ports.
  - (e) Connect the new hydraulic pipe assembly (10) (P/N 532.42.12.137) between the fitting on wing rib 1 (1) and the fitting on the fuselage (4).
  - (f) Use absorbent paper (Material No. P02-031) to clean any spilled hydraulic fluid.
- (2) Right EAL BSV modification:
  - (a) Put absorbent paper (Material No. P02-031) below the brake shuttle valve (5) at wing rib 1.
  - (b) Disconnect and remove the hydraulic pipe assembly (8) (P/N 532.42.12.176) from between the fitting on wing rib 1 (9) and the brake shuttle valve (5).


- (c) Disconnect and remove the hydraulic pipe assembly (6) (P/N 532.42.12.175) from between the brake shuttle valve (5) and the fitting on the fuselage (7).
  - (d) Install a new cap assembly (P/N 946.29.15.835) on the two empty brake shuttle valve (5) ports.
  - (e) Connect the new hydraulic pipe assembly (11) (P/N 532.42.12.139) between the fitting on wing rib 1 (9) and the fitting on the fuselage (7).
  - (f) Use absorbent paper (Material No. P02-031) to clean any spilled hydraulic fluid.
- (3) Bleed the brake system. Refer to AMM 12-B-32-40-00-00A-902A-A.

**C. Close Up**

- (1) Engage the emergency/parking brake.
- (2) Remove the chocks from the main wheels.
- (3) Remove all the equipment, tools and materials from the work area. Make sure that the work area is clean.
- (4) Close access panels 21PZ, 12EL and 12ER.



**D. Documentation**

- (1) Make an entry in the Aircraft Logbook to record the incorporation of this Service Bulletin.
- (2) Make sure that the Aircraft Logbook shows any new Pilatus Part Number(s) and/or Serial Number(s), as applicable.
- (3) Make an entry in the applicable Pilot's Operating Handbook (POH) / Airplane Flight Manual (AFM) to record the incorporation of this Service Bulletin
- (4) Make sure that all applicable Aircraft Documentation is updated.
- (5) Inform CAMP of the incorporation of this Service Bulletin and any new Pilatus Part Number(s) and/or Serial Number(s), as applicable. Send the completed CAMP feedback sheet to: [fax@campsystems.com](mailto:fax@campsystems.com)
- (6) Send the completed Pilatus feedback sheet with the serial number of the aircraft to Pilatus Aircraft Ltd Technical Support email: [techsupport.ch@pilatus-aircraft.com](mailto:techsupport.ch@pilatus-aircraft.com)



ICN-SBPIL-A-A32000000-A-S4080-05270-A-001-01

Brake Pipes - Pre Service Bulletin  
Figure 1 (Sheet 1 of 2)



ICN-SBPIL-A-A32000000-A-S4080-05271-A-001-01

Brake Pipes - Post Service Bulletin  
Figure 1 (Sheet 2 of 2)

INTENTIONALLY BLANK

## Feedback Sheet for the Accomplishment of SB 32-031

The purpose of this feedback sheet is to provide CAMP with the current information on each individual PC-12 aircraft. Please complete the grey cells as appropriate using black ink and block letters.

**Print out and send the completed feedback sheet to: [fax@campsystems.com](mailto:fax@campsystems.com)**

Aircraft MSN		Aircraft Registration		Total Airframe Hours	
Service Center				Total Landings	

### SB Accomplishment Information

We have embodied/accomplished this SB	<input type="checkbox"/>	Fully	<input type="checkbox"/>	Partially
<b>The undersigned confirms the accomplishment of this Service Bulletin</b>				
Date of accomplishment	Name		Signature	
Comments (procedure, kit quality, suggested improvements etc.)				

CAMP Feedback Sheet

INTENTIONALLY BLANK

## Feedback Sheet for the Accomplishment of SB 32-031

The purpose of this feedback sheet is to provide Pilatus with the current information on each individual PC-12 aircraft. Please complete the grey cells as appropriate using black ink and block letters.

**Send the completed feedback sheet to Pilatus Aircraft Ltd Technical Support email: [techsupport.ch@pilatus-aircraft.com](mailto:techsupport.ch@pilatus-aircraft.com)**

<b>Aircraft MSN</b>		<b>Aircraft Registration</b>		<b>Total Airframe Hours</b>	
<b>Service Center</b>				<b>Total Landings</b>	

### SB Accomplishment Information

We have embodied/accomplished this SB	<input type="checkbox"/>	Fully	<input type="checkbox"/>	Partially	<input type="checkbox"/>
<b>The undersigned confirms the accomplishment of this Service Bulletin</b>					
Date of accomplishment	Name		Signature		
<b>Comments (procedure, kit quality, suggested improvements etc.)</b>					

Pilatus Feedback Sheet

INTENTIONALLY BLANK