

Change of ECB Check in Before Engine Start Procedure

Temporary Revision

Temporary Revision No. 02371-016
To PC-24 Airplane Flight Manual
Report No. 02371

Manual Section

Section 4, Normal Procedures (Authority approved)

Validity

This Temporary Revision is valid for all PC-24 aircraft.

Filing Instructions

1. Print the Temporary Revision
2. Insert the Temporary Revision after the "TEMP. REV." tab
3. Record the incorporation of this Temporary Revision on the List of Temporary Revisions.

Important

Do not remove this Temporary Revision unless instructed to do so by:

- The highlights of a normal revision
- A new Temporary Revision which supersedes this one.

Reason for Issue

Change of ECB check.

Action

Revised content shown on next pages.

This page intentionally left blank

4-PF Preflight

On page 4-3-9, replace step 4 of the "Before Engine Start" procedure with the following text:

4. System Synoptic ECB..... Checked
- Search for *FAILED, TRIPPED or LOCKED ECBs*

This page intentionally left blank