

**Lufttüchtigkeitsanweisung
Consigne de navigabilité
Prescrizione di aeronavigabilità
Airworthiness directive**

HB 98-070

Inkraftsetzung
Mise en vigueur
Entrata in vigore
Effective Date

23.03.1998.

PC-9
(TCDS F56-22)

Betroffene Muster - Types concernés - Applicabilità - Models affected

PILATUS AIRCRAFT LTD. - All Model PC-9 airplanes, up to and including MSN 244.

Anlass/Massnahmen - Objet/Mesures - Oggetto/Provvedimenti - Subject/Action

LANDING GEAR SEAL UNIT - Replacement

Fristen - Délais - Scadenza - Compliance

Within 12 months after the effective date of this AD, unless accomplished previously.

Herkunft - Provenance - Provenienza - Origin

FOCA AD.

Bezugnahme - Référence - Riferimento - Reference

- PILATUS PC-9 Service Bulletin No.: 32-007, dated March 06,1998.

The applicable Service Bulletin may be obtained directly from :

PILATUS AIRCRAFT LTD
MARKETING SUPPORT DEPARTMENT
CH-6370 STANS
SWITZERLAND

TEL. No.: +41 41 619 6233
FAX No.: +41 41 610 3351

Bemerkungen - Observations - Osservazioni - Remarks

For detailed informations refer to page 2.

Rechtsmittelbelehrung
Voies de droit
Rimedi giuridici
Right to appeal

siehe TM Nr.
voir CT no.
vedi CT no.
see CT no.

F 02.020-80

Seite
Page 1
Pagina
Page

von
de 2
di
of

FOCA AD
HB 98-070

Lufttüchtigkeitsanweisung
Consigne de navigabilité
Prescrizione di aeronavigabilità
Airworthiness directive



BAZL Schweiz
OFAC Suisse
UFAC Svizzera
FOCA Switzerland

**HB 98-070 PILATUS AIRCRAFT LTD. - PC-9
LANDING GEAR SEAL UNIT - Replacement**

Applicability

PILATUS AIRCRAFT LTD. - All Model PC-9 airplanes, up to and including MSN 244.

Reason

This Airworthiness Directive (AD) is prompted by instances of improper landing gear strut extension after lift-off, caused by material deterioration of the landing gear strut seal. This condition, if not corrected, could cause damage to the airplane during landing gear retraction.

In order to correct the situation described this AD requires replacement of the existing landing gear seal unit with a new unit of improved design.

Compliance :

Within 12 months after the effective date of this AD, unless accomplished previously.

The actions required by this AD shall be done in accordance with the Accomplishment Instructions of PILATUS PC-9 Service Bulletin No.: 32-007, dated March 06,1998.

FOR FURTHER INFORMATION CONTACT:

FEDERAL OFFICE FOR CIVIL AVIATION (FOCA)
Type Certification Section (FM)
Maulbeerstrasse 9,
CH-3003 Berne
Switzerland

Fax (+41) 31 325 80 48

NOTE :

An exemption, deviation or extension of the compliance time may be used if approved by the National Airworthiness Authority.