

**PILATUS**  
**PC9**  
**MAINTENANCE MANUAL**

Task No.	Code	Task	Frequency
27507	A	Flap pivot arm assembly  Examine (Ref. 27-50-00, Page Block 601).	Threshold inspection at 30 April 2021 if installed before 30 April 2016, then every 5 years.  5 years if installed after 29 April 2016.
28106	A	Aerobatics Fuel Tank  Replace clamp (Ref. CMM 02082 28-10-01, Page Block 7001.)	6000 Flying hours
32107	F	Main Landing Gear Legs (MSN 001 thru 188, pre SB 32-004 and for Leg Housings not repaired in accordance with SB 32-003 or CMM No. 02070. Repaired Housings have to be examined in accordance with the intervals provided by Pilatus Aircraft Ltd. after repair was performed, Ref. CMM 32-10-04)  Remove for housing examination (Ref. 32-10-01, Page Block 401 and CMM No. 02070, 32-10-04).	2000 landings.
32108	A	Main Landing Gear Support Strut.  Examine. (Not Applicable if P/N 532.10.09.128 is installed), (Ref. 32-10-02, Page Block 601).	6 months.
35301	B1	Oxygen Cylinder  Replace (maximum life) (Ref. 35-10-02, Page Block 401).	15 years.
35302	B	Oxygen Cylinder P/N 897-18050 (if installed)  Replace (maximum life) (Ref. 35-10-01, Page Block 401).	15 years.
35303	B	Oxygen Cylinder P/N 6350-A25-WWC (if installed)  Replace (maximum life) (Ref. 35-10-01, Page Block 401).	24 years or 4380 cycles.
35304	A	Oxygen Cylinder  Remove for hydrostatic test (Ref. 35-10-02, Page Block 401 (All but RAAF)) (Ref. 35-10-01, Page Block 401 (RAAF only)).	5 years.

EFFECTIVITY: All

**05-05-01**

Page 2  
Feb 20/20