

Pilatus Aircraft Ltd
Pilatusstrasse 1
6371 Stans, Switzerland
Email: publications@pilatus-aircraft.com

TO HOLDERS OF:

PC-6 AIRCRAFT MAINTENANCE MANUAL

DOCUMENT NUMBER 01975

REVISION 39

DATED OCT 31/25

HIGHLIGHTS

Pages which have been added or revised are given below together with the highlights of the revision. Remove and insert the affected pages as listed.

	Remove	Insert	Reason for Change
Record of Revision			
	1 and 2	1 and 2	Updated.
Chapter 04 - Airworthiness Limitations			
04-LEP	1 and 2	1 and 2	Updated.
04-00-00	1 thru 8	1 thru 8	Add the Pitch Trim Relay to Chapter 27 time limits, with NOTE K. Add the Halon-Free Fire Extinguisher (Model P3APP003010D) to Chapter 25 time limits.
Chapter 05 - Time Limits / Maintenance Checks			
05-LEP	1 and 2	1 and 2	Updated.
05-10-10	1 thru 4	1 thru 4	Remove the Pitch Trim Relay from Chapter 27 time limits.
05-20-10	1 thru 4	1 thru 4	Add the Halon Alternative Fire Extinguisher (Model P3APP003010D) for Chapter 25.
05-23-01	1 thru 12	1 thru 12	Replace P09-006 with P02-021, for Chapter 21.
05-24-01	1 thru 14	1 thru 14	Replace P09-006 with P02-021, for Chapter 21.

Chapter 20 - Standard Practices

20-LEP	1 and 2	1 and 2	Updated.
20-31-00	1 thru 50	1 thru 52	Incorporated Master CML issues 26 thru 29: Removed part number from P01-031 that shall not be used. Introduced new products P04-050, P04-051, P07-088, P08-112 thru P08-116 and P09-142 thru P09-149 introduced. Added new part numbers to several products in table 4 - Jointing Compounds and Greases. Corrected status / note of P04-001, P04-004, P04-023, P04-027, P04-038 and P04-042. Updated product name and part number of P05-009. Changed part number of P07-031 to procurable. Removed duplicated material name of P08-017 (editorial). Changed product name of P08-059. Added new part number to P10-014. Replaced P10-020 with P10-027 thru P10-030.

Record of Revisions Sheet Record incorporation of this revision and date of incorporation.

Record of Temporary Revisions Sheet No change.