

Pilatus PC-6 AMM, Chapter 04-00-00, Document Number 01975 (IAC AR), issue 29 dated 28 February 2020 (approved by EASA on behalf of the Interstate Aviation Committee for aeroplanes registered in the Commonwealth of Independent States).

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 27 April 2020 as PAD 20-068 for consultation until 25 May 2020. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: AD@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: Pilatus Aircraft Ltd, Customer Support General Aviation, CH-6371 Stans, Switzerland, Telephone: +41 848 24 7 365, E-mail: techsupport.ch@pilatus-aircraft.com, Website: www.pilatus-aircraft.com.

SUPERSEDED

