



Process Aerotechnical Organisations

Your reference
Your communication
CH-8058 Zurich, June 23, 2003
Register 251.00
Our reference Claude Frei
Direct dialling +41 43 816 30 62
Direct fax +41 43 816 26 88
E-Mail claud.frei@bazl.admin.ch

Federal Aviation Administration
Suspected Unapproved Parts (AVR-20)
13873 Park Center Road, Suite 165
Herndon, VA 20171 USA

Suspected Unapproved Parts Notification

During an audit of a maintenance organisation the presence of parts that are suspected to have been manufactured and released using procedures that are not in conformity with the approved standards were detected by the Swiss Federal Office for Civil Aviation (FOCA).

The parts listed below are not eligible for installation in an aircraft.

Part Number: 301.40.3000
Serial Numbers: 11972/1 up to and including 11972/6
Description: Bubble window
Eligibility: AS350 Ecureuil
Manufacturer: Mecaplex; Approval Ref. Number 049 JAA Form One
Certificate Ref. Number: 1575

If any of these parts have been installed in an aircraft, they must be replaced immediately with airworthy parts. If any of these parts are discovered in stock, they are not to be used on aircraft before it has been ascertained that they conform to the aircraft type design.

Please report back to this office of any actions taken.

Yours sincerely,
Federal Office for Civil Aviation Process
Aerotechnical Organisations

A handwritten signature in black ink, appearing to read 'C. Frei', with a small dot above the 'i'.

Claude Frei, Inspector

Enclosures: JAA Form One No. 1575

Copies:

Ameritrans Cargo
c/o Helicargo Trading Inc. Attn: Mr Luis
G. Angel 7102 N.W. 50 Street Miami
33166-5636, Fla USA