


BEARINGS, TRACKS AND
RADIALS ARE MAGNETIC
DISTANCES IN NM
ALTITUDES IN FT
VAR 3° E 2020.5

RNP 1
GNSS or DME/DME/IRU required
RF required



COMMUNICATION FAILURE PROCEDURE:

- Set transponder on code 7600.
- Cross GERSA / RULAR / VEBIT climbing to / at last received and acknowledged FL but not below MCA*.
- Continue climb to FPL FL.

***)** Leave last received and acknowledged FL or ALT earliest three minutes after airborne.

COR: new chart (WEF DDMMYYYY)