




RNAV 1
GNSS or DME/DME/IRU required



CLOSE-IN OBST: Trees on the right
up to 1584 until 0.4 NM after DER.



COMMUNICATION FAILURE PROCEDURE:

- Set transponder on code 7600.
- Cross GERSA / RULAR / VEBIT climbing to / at last received and acknowledged FL but not below MCA*.
- Continue climb to FPL FL.

***)** Leave last received and acknowledged FL or ALT earliest three minutes after airborne.